# **Requirements document**

SQUID

Helsinki 23rd February 2005 Software Engineering Project UNIVERSITY OF HELSINKI Department of Computer Science

### Course

581260 Software Engineering Project (6 cr)

### **Project Group**

Mikko Jormalainen Samuli Kaipiainen Aki Korpua Esko Luontola Aki Sysmäläinen

#### Client

Lauri J. Pesonen

### **Project Masters**

Juha Taina Jenni Valorinta

#### Homepage

http://www.cs.helsinki.fi/group/squid/

### **Change Log**

Version	Date	Modifications
0.1	9.2.2005	First version (Aki Sysmäläinen)

# Contents

1	Intr	Introduction														1																					
	1.1	Glossa	ary	1.	•	•		•	•	•			•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	1
2	Ove	rview																																			1
3	Use	Use cases															1																				
	3.1	Measu	uri	ng	, <b>.</b>					•		•		•	•	•	•						•	•	•	•	•	•	•	•	•	•	•	•	•		1
	3.2	File fo	orn	na	ts			•		•					•	•	•						•	•		•	•	•	•	•	•	•			•		3
	3.3	Functi	ior	nal	ity	7				•		•			•	•	•						•	•		•	•		•	•	•	•		•	•		5
	3.4	AF see	qu	en	ce	S		•	•	•			•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	5
4	Usei	r requir	rer	ne	ente	S																															6
	4.1	Functi	ior	nal	re	qu	iire	em	en	ts					•	•	•						•	•		•	•	•		•	•	•			•		6
	4.2	Qualit	tyı	rec	qui	re	me	ents	S								•										•	•		•					•		8
	4.3	Enviro	oni	me	ent	•		•									•							•			•	•	•						•		8
	4.4	Mainta	air	nał	oili	ity	, •									•	•										•				•	•					8
	4.5	Restrie	cti	on	IS								•			•	•	•				•		•		•		•	•	•	•	•	•			•	8
5	Syst	System requirements / Functions 8																																			
	5.1	System	m 1	res	stri	cti	ion	IS	•	•			•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	9
6	Usei	ser interface 9															9																				
	6.1	Goal d	der	iv	ed	us	se c	cas	es				•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	9
7	Arc	hitectur	re	ov	'er	vie	ew																														9
8	Exte	ernal in	nte	rfa	ace	es																															9
	8.1	Hardw	vai	e	coi	ntr	ol	pro	oto	00	cls					•	•					•	•	•			•	•	•		•	•		•	•	•	9
		8.1.1	]	Ha	ind	lle	r c	on	tro	ol p	pro	oto	occ	ol	•	•	•						•	•	•	•	•	•	•	•	•	•	•	•	•		9
		8.1.2	]	Me	eas	sur	en	nen	nt r	ea	ıdi	ng	g p	ro	to	C	ol					•	•	•		•	•	•		•	•	•		•	•		9
		8.1.3	]	De	ema	ag	net	tize	er	co	ntı	rol	l p	ro	to	c	ol	•				•	•	•		•		•	•	•	•	•	•			•	9
9	Vali	dation																																			9

## **1** Introduction

This document describes client requirements and system requirements for a SQUID magnetometer program that will be designed and implemeted as a software engineering student project at University of Helsinki at the Computer Science Department. The client is the Department of Geophysics.

This document serves as a contract between client and us..

Expected readership of this document here..

## 1.1 Glossary

Technical terms here ..

## 2 Overview

A brief overview of the problem domain..

## **3** Use cases

Describes planned use cases for the program. Derived from user interface prototype and user requiremets. All use cases are made by "the user" in program main screen, unless otherwise noted.

Format for uce cases:

UC0: Uce case number and title
Scenario a: First scenario for doing the use case
Scenario b: Second scenario for doing the use case
Precondition: Preconditions for use case
Postcondition: Postconditions for use case
Error condition: Error handling, mainly if anything special needs to be done

### 3.1 Measuring

UC1: Do single step measuring without demagnetization

Scenario a: Enter as next AF demagnetization step "0" or empty (default for new projects), meaning no demagnetization, and click "Single step".Precondition: Open AF project, sample in sample holder.Postcondition: Sample measured, results on screen.

**Error condition:** The program shall let the user know if something went wrong.

#### UC2: Do single step measuring with demagnetization

**Scenario a:** Enter as next AF demag step anything greater than zero, and click "Single step".

Precondition: Open AF project, sample in sample holder.

**Postcondition:** Sample demagnetized (possibly ruined) and measured, results on screen. **Error condition:** The program shall let the user know if something went wrong, and, should the demagnetization field not be coming down, warn user with an alarm sound :)

#### UC3: Do automatic demagnetization-measuring sequence

**Scenario a:** Enter the AF sequence (see 3.4 for ways to enter it) and click "Measure". **Precondition:** Open AF project, sample in sample holder.

**Postcondition:** Sample demagnetized according to entered AF sequence (possibly ruined) and measured after each demagnetization, results on screen.

**Error condition:** The program shall let the user know if something went wrong, and, should the demagnetization field be uncalm, warn user with an alarm sound x)

#### UC4: Pause automatic measuring sequence

Scenario a: While measure sequence is running, click "Pause".

Precondition: Ongoing measure sequence.

Postcondition: Measure sequence halts after current step is done, results on screen.

**Error condition:** Program tells if sequence can't be paused (and something has gone terribly wrong).

#### UC5: Abort automatic measuring sequence

Scenario a: While measure sequence is running or paused, click "Stop immediately". **Precondition:** Ongoing or paused measure sequence.

**Postcondition:** Measure sequence halts immediately [and program enters "fully manual" mode?]

**Error condition:** Program tells if sequence can't be aborted (and something has gone terribly wrong).

#### UC6: Do thellier measuring

**Scenario a:** Click "Single step". (Temperature can be entered later, as it won't affect measuring.)

Precondition: Open TH project, sample in sample holder.

Postcondition: Sample measured, results on screen.

Error condition: As usual.

#### UC7: Do thermal measuring

[Exactly the same as thellier?] **Scenario a:** Click "Single step". (Temperature can be entered later, as it won't affect

measuring.)Precondition: Open TH project, sample in sample holder.Postcondition: Sample measured, results on screen.Error condition: As usual.

#### UC8: Measure magnetometer ground noise

[2005-02-23 not in current UI proto, nor planned for implementation]Scenario a: Click "Ground noise" and "Calibrate".Precondition: None.Postcondition: Ground noise measured, results on screen.

#### UC9: Measure empty sample holder noise

[2005-02-21 In current UI prototype, "Noise" actually does sample holder noise measuring.]Scenario a: Click "Holder noise" and "Calibrate".Precondition: Empty sample holder.

Postcondition: Holder noise measured, results on screen.

#### UC10: Fully manual measuring

Demagnetize X, Y or Z axis
item Measure X, Y or Z axis
Scenario a: Click any of the manual control components [2005-02-21 at right third of UI proto].
Precondition: Manual mode enabled.
Postcondition: Manual action done, result on screen.

#### UC11: Enable manual mode

Scenario a: Click "Manual" checkbox above the manual control components. Precondition: No ongoing measurement. Postcondition: Manual mode enabled.

### **3.2** File formats

UC12: Automatically save all measurement cycles in project [.dat?] fileScenario a: Make any measurement action.Precondition: Open project file.Postcondition: After measurement is done, new results appended to project file.

UC13: Save standard sample measurement results in .std file Scenario a: Click "Standard sample", "Calibrate". Precondition: No ongoing measurement. **Postcondition:** After standard sample measurement is done, new results appended to predefined .std file.

#### UC14: Export project data into .dat file

**Scenario a:** In project explorer file list, right-click on desired project file, click "Export .dat in current directory".

**Scenario b:** In project explorer file list, right-click on desired project file, click "Export .dat to disk drive A:".

**Scenario c:** In project explorer file list, right-click on desired project file, click "Export .dat...", chooce directory and filename to export.

Precondition: At least 1 project file in current (selected) directory.

Postcondition: Project data exported to .dat file.

Error condition: Notify if file error occurs (such as no disk in A: drive).

#### UC15: Export (thellier) project data into .tdt file

**Scenario a:** In project explorer file list, right-click on desired project file, click "Export .tdt in current directory".

**Scenario b:** In project explorer file list, right-click on desired project file, click "Export .tdt to disk drive A:".

**Scenario c:** In project explorer file list, right-click on desired project file, click "Export .tdt...", chooce directory and filename to export.

Precondition: At least 1 project file in current (selected) directory.

Postcondition: Project data exported to .tdt file.

Error condition: Notify if file error occurs (such as no disk in A: drive).

#### UC16: Export single measurement details into .srm file

**Scenario a:** In measurement result table, right-click on desired measurement line, click "Export .srm in current directory".

**Scenario b:** In measurement result table, right-click on desired measurement line, click "Export .srm to disk drive A:".

**Scenario c:** In measurement result table, right-click on desired measurement line, click "Export...", chooce directory and filename to export.

Precondition: At least 1 measurement result in current project.

Postcondition: Measurement details exported to .srm file.

Error condition: Notify if file error occurs (such as no disk in A: drive).

#### **UC17: Print measurement results**

**Scenario a:** Click "Print...", "Measurement results". [2005-02-23 propably gone in current UI prototype; implementation priority low]

Precondition: Open project.

Postcondition: Measurement results printed via [Java] standard printing window.

Error condition: Let know if printing error occurs.

#### UC18: Print graph sheet (with 7 different graphs; described elsewhere)

**Scenario a:** Click "Print...", "Grap sheet". [2005-02-23 propably gone in current UI prototype; implementation priority low]

Precondition: Open project.

Postcondition: Measurement results printed via [Java] standard printing window.

Error condition: Let know if printing error occurs.

### 3.3 Functionality

UC19: Create new project [.dat file?]

UC20: Load project [.dat file?]

#### UC21: Append measurement results to project [.dat file?]

#### UC22: Panic abort operation instantly

When any measuring action, click "Stop immediately".

**Precondition:** Single step measuring or ongoing measure sequence. **Postcondition:** All demagnetization and measuring halts immediately [and program enters "fully manual" mode?]

**Error condition:** Program tells if measuring can't be aborted, meaning something has gone terribly wrong.

## 3.4 AF sequences

As in automatic demagnetization-measuring sequences, or Alternating Field sequences

UC23: Insert AF sequence with start-step-stop values

UC24: Load AF sequence

UC25: Save AF sequence

UC26: Edit AF sequence on-the-fly

UC27: Edit stored AF sequences

UC28: Rename stored AF sequence

UC29: Delete stored AF sequence

## **4** User requirements

Goals of the software set by client ..

#### 4.1 Functional requirements

Identifier: R1 Name: Basic Description: Able to control Squid-magnetometer and make measurements with it. Priority: 1

Identifier: R2 Name: Saving Description: Measurements can be saved in .dat, .dtd and .srm files. Priority: 1

Identifier: R3 Name: Auto saving Description: Program will save mesurement data after every measurement step. Priority: 1

Identifier: R4 Name: Loading Description: Saved mesurement date can be loaded into program. Priority: 2

Identifier: R5 Name: Filemanagement Description: New data can be added to existing datafiles. Priority: 2

Identifier: R6 Name: Numeric presentation of data Description: Program shows measurement data in numbers. Priority: 1 Identifier: R7 Name: Graphic presentation of data Description: Program draws graphs from measurement data. Priority: 3

Identifier: R8 Name: Editing Description: Ability edit data afterwards. Priority: 2

Identifier: R9 Name: Recalculation Description: Recalculate based on changed data. Priority: 2

Identifier: R10 Name: Control Description: Ability to stop any action immediately. Priority: 1

Identifier: R11 Name: Sequence Description: Able to create measuring sequences with several different sized steps. Priority: 2

Identifier: R12 Name: Sequence control Description: Able to stop sequence after current step. Priority: 2

Identifier: R13 Name: Hotkeys Description: Possibility to create and change hotkeys. Priority: 4

Identifier: R14 Name: Manual Description: Able to operate magnetometer manually. Priority: 2

ReqIdR15 Name: Calibration Description: Magnetometer must be calibrated every 24h... **Priority:** 2

ReqIdRXX Name: Description: Priority:

## 4.2 Quality requirements

Identifier: QR1 Name: Ease of use Description: Program should be easy to use for first time users. Priority: 1

Identifier: QR2 Name: Help pages Description: Program should have good help pages. Priority: 3

### 4.3 Environment

#### 4.4 Maintainability

### 4.5 Restrictions

Program will be used in normal PC which is connected to magnetometer. Taking into account rapid phase of computer evolution it is possible that computer in which program is used can change, accordingly the program should be able to be installed by outsiders. We need not prepare to changing of magnetometer, as new magnenetometer will probably have its own program.

# 5 System requirements / Functions

Specific explanation of the functions to be implemented

## 5.1 System restrictions

## **6** User interface

Overview of UI described here ..

## 6.1 Goal derived use cases

## 7 Architecture overview

## 8 External interfaces

Interface to existing software and use of it described here..

## 8.1 Hardware control protoocls

- 8.1.1 Handler control protocol
- 8.1.2 Measurement reading protocol
- 8.1.3 Demagnetizer control protocol

## 9 Validation

Description of how to validate the set requirements.